

IC REJECTION LETTER**No. CBSE/AFF/SL-00223-2526/2025-26****Dated:06/09/2024**

The Manager,
 NIMAI PUBLIC SCHOOL ONNALVADI VILLAGE RAYAKOTTAI ROAD
 HOSUR TALUK
 KRISHNAGIRI , TAMILNADU
 635109

Sub: Category of school applied for (**Fresh Affiliation Up to Secondary Level**) -regarding.

Ref: Application No.SL-00223-2526 dated 29/02/2024

This is with reference to school application No.SL-00223-2526 dt.29/02/2024 on the subject cited above

In this connection, I am directed to inform that your application has been rejected on the following grounds.

1	From the salary details provided by the school on “Other Upload Files” of SARAS portal and through email dated 30-07-2024, it is noticed that salary to NTTs and other teaching faculty are being paid less than the minimum prescribed wage of the state government.
2	Height of concrete boundary wall is seen less than the prescribed height (6 feet). The iron grills are fixed on the concrete wall of (approx. 3 - 4 feet) to make the prescribed height (IC video ref 11:16).
3	CWSN facility like ramp at the entrance is not seen in the videography.
4	The grab bars are not placed appropriately on CwSN toilets. The wash basin is not seen inside the CWSN toilets. Separate CwSN toilets for boys and girls as per norms of RPwD Act and Board’s guidelines are not available on every floor.
5	The school has constructed a ramp to access upper floor, but there is step between floor and entry to the ramp which will be difficult to a wheelchair bound person.
6	The inside view of Maths lab is not properly shown in the videography in terms of demonstration table, seating facility, storage facility etc.
7	Composite lab does not have permanent workstations separately for Physics, Chemistry and Biology sections with appropriate fixture like sinks with water connection, piped gas supply on the demonstration tables. There is no storage facility. Safety features like exhaust fan and emergency exit are also not seen in the lab.
8	Library is seen understocked. Reading area for students is inadequate and there is no reading space for staff.
9	Indoor and outdoor sports facilities are seen inadequate. Some indoor sports items are placed on ground which is not as per norms.
10	IC has suggested that (i) co-curricular activities to be initiated (ii) the school is to fix iron bars in corridor wall of first floor as a safety measure.
11	The school is advised to upgrade its labs, library, sports facilities and CWSN infrastructure in the light of SoPs, and follow the circular No.05/2023 for CwSN facilities before seeking grant of affiliation.

Further, as per clause 10.5.2 of Affiliation Bye-Laws, 2018, the fee deposited will not be refunded or adjusted irrespective of the grounds on which the application has been rejected even if the school has not been inspected.

The school may seek a review of the above decision of the Board within 15 days on SARAS portal.

DEPUTY SECRETARY/JOINT SECRETARY (AFF.)

This is an electronically generated document. It does not need any signature.

To verify the authenticity of the document , please visit

(<http://www.saras.cbse.gov.in/saras/AffiliatedList/ListOfSchdirReport>).

Print