

CBSE COMPLIANCE CLARIFICATION

S No	Deficiency mentioned by CBSE	Justification / Action by School
1)	<p>Deficiency Point No: 1</p> <p>From the salary details provided by the school on “Other Upload Files” of SARAS portal and through email dated 30-07-2024, it is noticed that salary to NTTs and other teaching faculty are being paid less than the minimum prescribed wage of the state government.</p>	<p>Salary revised for teaching faculty as per the norms. Kindly refer the mandatory disclosure. Kindly refer the mandatory discloser , infra structure s.no</p> <p>https://nimaipublicschool.in/df/salaries%20details.pdf</p>
2)	<p>Deficiency Point No: 2</p> <p>Height of concrete boundary wall is seen less than the prescribed height (6 feet). Their on grills are fixed on the concrete wall of (approx. 3 - 4 feet) to make the prescribed height (IC video ref 11:16).</p>	<p>Height of the concrete boundary wall has raised 6 feet to make the prescribed height. Kindly refer the link</p> <p>https://www.youtube.com/watch?v=w3cIZeJJ8GE</p>
3)	<p>Deficiency Point No: 3</p> <p>CWSN facility like ramp at the entrance is not seen in the videography.</p>	<p>Ramp at the entrance of CWSN toilet was shown in the video. Kindly refer the link</p> <p>https://www.youtube.com/watch?v=bGPueoqTvkc</p>
4)	<p>Deficiency Point No: 4</p> <p>The grab bars are not placed appropriately on CwSN toilets. The wash basin is not seen inside the CWSN toilets. Separate CwSN toilets for</p>	<p>Grab bars are placed appropriately on CWSN toilet for both girls and boys on every floor . Kindly refer the link</p>

	boys and girls as per norms of RPwD Act and Board's guidelines are not available on every floor.	https://www.youtube.com/watch?v=bGPueoqTvkc
5)	<p>Deficiency Point No: 5</p> <p>The school has constructed a ramp to access upper floor, but there is step between floor and entry to the ramp which will be difficult to a wheelchair bound person.</p>	<p>We have reconstructed the step into the ramp that connects to the ramp on the first floor. Kindly refer the link</p> <p>https://www.youtube.com/watch?v=G7XvUjole2w</p>
6)	<p>Deficiency Point No: 6</p> <p>The inside view of Maths lab is not properly shown in the videography in terms of demonstration table, seating facility, storage facility etc.</p>	<p>The inside view of math lab is properly shown in the videography in terms of demonstration table , seating facility , storage facility etc. Kindly refer the link</p> <p>https://www.youtube.com/watch?v=4B3ma91to2I</p>
7)	<p>Deficiency Point No: 7</p> <p>Composite lab does not have permanent workstations separately for Physics, Chemistry and Biology sections with appropriate fixture like sinks with water connection, piped gas supply on the demonstration tables. There is no storage facility. Safety features like exhaust fan and emergency exit are also not seen in the lab.</p>	<p>Permanent workstations for physics, chemistry, and biology are ready, equipped with appropriate fixtures such as sinks with water connections, piped gas supply on the tables, and adequate storage facilities. Exhaust fans and emergency exits have also been prepared. Kindly refer the link</p> <p>https://www.youtube.com/watch?v=qrA7ERnu-Dg</p>

8)	<p>Deficiency Point No: 8</p> <p>Library is seen understocked. Reading area for students is inadequate and there is no reading space for staff.</p>	<p>The library is stocked, a reading area for students has been arranged, and a separate space for staff has been provided. Kindly refer the link</p> <p>https://www.youtube.com/watch?v=9KNRCwQmS3k</p> <p>library stock register</p> <p>https://nimaipublicschool.in/pdf/LibraryRegister.pdf</p>
9)	<p>Deficiency Point No: 9</p> <p>Indoor and outdoor sports facilities are seen inadequate. Some indoor sports items are placed on ground which is not as per norms.</p>	<p>Sports items are placed on proper racks, and indoor and outdoor sports facilities are made available for the benefit of the students. Kindly refer the link</p> <p>https://www.youtube.com/watch?v=CJ3d0B746Q4</p>
10)	<p>Deficiency Point No: 10</p> <p>IC has suggested that</p> <ul style="list-style-type: none"> (i) co-curricular activities to be initiated (ii) the school is to fix iron bars in corridor wall of first floor as a safety measure. 	<p>Co-curricular activities are planned and initiated. Iron bars have been fixed in the first-floor corridor as a safety measure. Kindly refer the link</p> <p>Co curricular activities</p> <p>https://nimaipublicschool.in/pdf/merged1.pdf</p> <p>safety grills</p> <p>https://www.youtube.com/watch?v=I8oyzuk3NzU</p>